
readout errors on SaSeq test stands

readout with 4 full chains has error rate 4 ev./200k events. typical failure:





wrong chip IDs in first 20 chips! (everything else fine)





explanation for this type of error

VME bus errors during DMA data transfer SaSeq → Bit3

- data transfer fails
- spreadsheet sees previous event still in memory
- repeated events (1 SaSeq), resp. identical data in master/slave chains (2 SaSeqs)

Recovery times after each VME error:

full chain test stand: 4 faulty events before recovery burn-in test stand: 1800 faulty events before recovery!

Standard spreadsheet ignores VME errors

→ repeated events!



VME bus error overview

| test stand | Sara's | Sara's | Burn-in | Cecil's |
|------------|------------|------------|------------|------------|
| | full chain | purple crd | purple crd | purple crd |
| errors in | YES | YES | YES | ??? |
| DMA mode | 1 L3 | 1 L3 | 1 LO | ::: |
| errors in | YES | YES | NO | NO |
| non-DMA | I L3 | ILS | INO | INO |

Cecil's test stand cannot do DMA NO error means none in 5–10 million events

readout errors: conclusion

preliminary conclusion: probably two effects

- minor problem with Bit3 DMA mode?
- defective crate and/or Bit3 in Sara's test stand?


in any case:

besides VME bus errors, not a single readout error seen in millions of events with 4 full chains!

ready for the "big thing" (the electrical stave)

first look into stave readout

first readout of 1/2 electrical stave (10-10 axial and 20-20 axial mounted on stave core)




well, at least it works... (no readout errors/1000 events)



first look into stave readout (contd.)

stave readout with purple card:



- about 1% failed events (not yet investigated)
- one hybrid occasionally reads all channels 0 ADC

conclusions

work in progress...

but the readout is in very good shape!